### NATIONAL UNIVERSITY OF SCIENCE AND TECHNOLOGY

# FACULTY OF INDUSTRIAL TECHNOLOGY DEPARTMENT OF ELECTONIC ENGINEERING BACHELOR OF ENGINEERING (HONS) DEGREE

# Final Examination January 2011

### **TEE 2102**

## **ELECTRICAL MACHINES**

#### **Duration of Examination - 3 Hours**

#### INSTRUCTIONS TO CANDIDATES

- 1. Answer any **FIVE** questions only.
- 2. Each question carries 20 marks.
- 3. Show your steps clearly in any calculation.
- 4. Start the answers for each question on a fresh page.

## Question 1

The diagram in Figure 1 shows a two-pole generator.




Figure 1

The magnetic circuit of the machine has the following dimensions:

Each pole (cast steel with  $\mu_r = 398$ ):

Magnetic length = 10cm

Cross-section =  $400 \text{cm}^2$ 

Each air gap:

Length = 0.1cm

Cross section =  $400 \text{cm}^2$ 

Armature (Silicon Steel with  $\mu_r = 110$ ):

Length = 20cm

Average cross section =  $400 \text{cm}^2$ 

Yoke (cast steel with  $\mu_r = 390$ ):

Length = 160cm

average cross section = 200cm<sup>2</sup>

Half the exciting winding is on each pole.

a) Draw the magnetic equivalent circuit.

[7 marks]

- b) How many ampere-turns per pole are required to produce a flux density of 1.1T in the air gaps? [10 marks]
- c) Give reasons why the stator and rotor of a DC machine are not laminated. [3 marks]

Question 2

Three single phase 100kVA, 2300/460V, 60Hz transformers are connected to form a three-phase, 2300/460V transformer bank. The equivalent impedance of each transformer referred to the low-voltage side  $0.045 + j0.16\Omega$ . The transformer is connected to a three phase source through three phase feeders, the impedance of each feeder being  $0.5 + j1.5 \Omega$ . The transformer delivers full load at 460V and 0.85 power factor lagging.

a) Draw a schematic diagram showing the transformer connection and the feeder impedances.

[7 marks]

b) Determine the single phase equivalent circuit.

[6 marks]

c) Determine the sending end voltage for the three phase source.

[3 marks]

d) Determine the transformer winding currents.

[4 marks]

Question 3

A 40kW, 200V, 1800rpm shunt motor requires a starter box. During the start up, the armature current is constrained within the range 200 to 400A. The armature circuit resistance is  $0.15\Omega$ .

a) Determine the start current if the starter box is not used.

[4 marks]

b) Determine the required number of resistors and the value of each in the starter box.

[16 marks]

**Question 4** 

A 440V, 60Hz, six pole, three phase induction motor is taking 50kVA at 0.8 power factor and is running at a slip of 2.5%. the stator copper losses are 0.5kW and rotational losses are 2.5kW.

Calculate the rotor copper losses

[4 marks]

b) Calculate the shaft power

c) Calculate the efficiency [4 marks]

Calculate the shaft speed

[4 marks]

Calculate the shaft torque

[4 marks]

### Question 5

A three-phase 14kV, 10MVA, 60Hz, two-pole, 0.85 power factor, star connected, synchronous generator has  $X_s = 20\Omega$  per phase and  $R_s = 2\Omega$  per phase. The generator is connected to an

- Determine the excitation voltage at the rated condition. Draw the phasor diagram for this condition. [8 marks]
- Determine the power angle at the rated condition.

[5 marks]

Determine the speed of the generator.

[3 marks]

Explain how a synchronous machine can be used to correct power factor. d)

[4 marks]

## Question 6

A DC shunt machine (24kW, 240V, 1000rpm) has  $R_a = 0.12\Omega$ ,  $N_f = 600$  turns per pole. The machine is operated as a separately excited DC generator and is driven at 1000rpm. When I<sub>f</sub> = 1.8A, the no load terminal voltage is 240V. when the generator delivers full-load current, the terminal voltage drops to 225V.

- Determine the generated voltage and developed torque when the generator deliver full load. a) [8 marks]
- b) Determine the voltage drop due to armature reaction.

[5 marks]

The full load terminal voltage can be made the same as the no load terminal voltage by c) increasing the field current to 2.2A or by using a series winding on each pole. Determine the number of turns per pole of the series winding required if I<sub>f</sub> is kept constant at 1.8A

[7 marks]

# END OF PAPER